







The elevator trim does not plug in, try and align it as best you can. The backing plate slips in behind the elevator door plate




















2nd Floor Complete!

The elevator trim does not plug in, try and align it as best you can. The backing plate slips in behind the elevator door plate and glues to the back of the door plate

### 2ND FLOOR COMPLETE



Try to align the roof trim so that it covers the slots underneath. The trim piece is

smaller than the base plate, you should have a 2mm 'gap' so that the trim is 'inset'



CONGRATULATIONS!

MODEL COMPLETE!

