



# TRAB007 CORNELIUS ADDITIONAL FLOOR




STEP 1



STEP 2



STEP 3



The elevator trim does not plug in, try and align it as best you can. The backing plate slips in behind the elevator door plate

Additional Floor Complete

