



TRAB005 CORNELIUS APARTMENTS




STEP 1



STEP 2




STEP 3



The elevator trim does not plug in, try and align it as best you can. The backing plate slips in behind the elevator door plate


GROUND FLOOR COMPLETE!




TRAB005 CORNELIUS APARTMENTS




STEP 4



STEP 5




STEP 6



The elevator trim does not plug in, try and align it as best you can. The backing plate slips in behind the elevator door plate


STEP 7




TRAB005 CORNELIUS APARTMENTS




1ST FLOOR COMPLETE!




STEP 8



STEP 9



STEP 10





The elevator trim does not plug in, try and align it as best you can. The backing plate slips in behind the elevator door plate

TRAB005 CORNELIUS APARTMENTS



ROOF COMPLETE!

STEP 11



CONGRATULATIONS!

Model complete!

